



THE POLISHING MACHINE / BUFFING MACHINE


SIDE VIEW




FRONT VIEW



CORRECT - The work should be pushed gently against the rotating mop. It should be held firmly in both hands and moved continuously left and right, against the **lower part** of the mop.



UNSAFE - This is a dangerous way to hold the work, as its top corner is about to be caught by the rotating mop. The work will be 'wrenched' from the machine operators hands.



UNSAFE - The work is about to be pressed against the top part of the mop. This is dangerous, as the work will be 'ripped out' of the machine operators hands. It will fly at high speed, towards him/her.